

DEPARTMENT OF TRANSPORTATION**DIVISION OF ENGINEERING SERVICES**

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-021258**Date Inspected:** 07-Jul-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Lie Hua Jie**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Segment Assembly**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Ramesh Gade, was present during the times noted above for observations relative to the work being performed.

This QA Inspector observed the following work in progress:

Cross Beam CB11

This QA Inspector performed verification Ultrasonic Testing (UT) in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a data sheet that Caltrans QA generates after performing a joint inspection. The members are identified as the CB11-W DP to SP weld. ABF Report No: UT-CB11-01457

The weld designations reviewed are as follows:

CB202A-011-014

OBG Segment 9BE-9CE

During in process visual inspection of 9BE-9CE, This QA Inspector observed ABF Quality Assurance (QA) personnel performing Magnetic Particle Testing (MT) on Side Panel 'T' Ribs holdback area welds of Cross Beam side. See attached photograph Pic_001

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

OBG Segment 9BE-9CE

Flux Core Arc Welding (FCAW) in the 1G position of Bike Path side Bottom Panel to Side Panel, weld # 9CE-SEG054A-014 as per Repair Report # B-WR-13818. The welder is identified as 220069. ZPMC Quality Control (QC) is identified as Wang Li Yang. The welding variables recorded by QC appeared to comply with WPS-345-FCAW-1G(1F)-FCM-Repair. See attached photograph Pic_002



Summary of Conversations:

No relevant conversations reported on this date.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (+86)15000 42 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Gade,Ramesh	Quality Assurance Inspector
Reviewed By:	McClendon,Timothy	QA Reviewer
